	IHC CDF I	Dredge Pro	oject : Air N	Aonitoring A	larm Response Log
Air Monitor	ing Station: \Box M1	□ M2	□ M3	X M4	
Cerex U	nit (Naphthalene) 🛛 TI	hermo Unit (Pa	rticles) 🗆 F	PID Monitor	
Date & Tim	e of alarm: <u>11/15/2012_9</u>	:30 PM	Email sent	to site Technician	(Yes) or No).

1. Alarm cause by:

Loss of PowerLoss of Radio CommunicationOut of CalibrationUV AlignmentXBlockage in Air TubeAir QualityOther:

- 2. Corrective Actions taken (Yes) or No).
- 3. Dredging suspended (Yes or No)).
- 4. Alarm logged in air monitoring action spreadsheet. (Yes) or No).

Description of Action Taken:

M4 Thermo Unit alarm was caused by spiders inside of the naphelometer and paper filter. The spiders were vacuumed out of the inlet tube and naphelometer. Unit was recalibrated at 7:30 AM 11/16/12 and inspected at 9:00 AM 11/16/12 to confirm proper function.

