IHC CDF Dredge Project : Air Monitoring Alarm Response Log						
Air Monitoring Station:	\Box M1	X M2	□ M3	□ M4	□ Dock	
Air Monitoring Instrument:						
Cerex Unit (Naphthalene)			articles)	□ PID Monitor		
Date & Time of alarm: <u>2/19/2013 12:00</u>			Email sent	to site Technician?	(Yes) or No)	
Technician responded to the alarm; Scott Peterson						
1. Was dredging occurring at the time of the alarm?					(Yes or No	
2. Alarm caused by:						
Loss of Power						
Loss of Radio Communication						
Out of Calibration						
UV Alignment						
Blockage in Air Tube						
X Air Quality						
X Other: Weat	her					
3. Corrective Actions taken? (Yes or No)						
					(Yes or No)	
4. Dredging suspended?					(Yes or No))	
5. Alarm logged in air monitoring action spreadsheet?					(Yes or No)	

Description of Action Taken:

Thermo units alarmed for unknown reasons. Units were inspected at 12:30 PM 2/19/13 to confirm proper functions. Units were re-inspected at 3:30 AM 2/19/13 to confirm proper functions.