IHC CDF Dredge Project : Air Monitoring Alarm Response Log						
Air Monitoring Station:	X M1	□ M2	□ M3	□ M4	Dock	
Air Monitoring Instrument:						
Cerex Unit (Naphthalene)			articles)	□ PID Monitor		
Date & Time of alarm: <u>4/07/2013 4:45 AM</u>			Email sent	to site Technician?	(Yes) or No)	
Technician responded to the alarm; Scott Peterson						
1. Was dredging occurring at the time of the alarm?					(Yes) or No)	
2. Alarm caused by:						
Loss of Power						
Loss of Radio Communication						
Out of Calibration						
UV Alignment						
Blockage in Air Tube						
X Air Quality						
X Other: Weat	her					
3. Corrective Actions taken?					(Yes or No)	
4. Dredging suspended?					(Yes or No))	
5. Alarm logged in air monitoring action spreadsheet?					(Yes or No)	

Description of Action Taken:

Thermo units alarmed from high winds kicking up dust. Units were inspected at 7:30 PM 4/8/13 to confirm proper functions. Units were re-inspected at 3:30 PM 4/8/13 to confirm proper functions.