## IHC CDF Dredge Project: Air Monitoring Alarm Response Log

(Yes or No

Air Monitoring Station:	X M1	□ M2	□ M3	□ M4	□Dock
Air Monitoring Instrument	:				
☐ Cerex Unit (Naphthalene)			articles)	☐ PID Monitor	
Date & Time of alarm: <u>4/30/2013 1:15 PM</u>			Email sent	t to site Technician? (Yes) or No)	
Technician responded to the alarm; Scott Peterson					
1. Was dredging occurring at the time of the alarm?					((Yes) or No)
2. Alarm caused by:					
Loss of Pow	er				
Loss of Radio Communication					
Out of Calibration					
UV Alignment					
X Blockage in Air Tube					
X Air Quality					
Other: Weat	ther				
3. Corrective Actions taken?					(Yes or No)
4. Dredging suspended?					(Yes or (No))

## Description of Action Taken:

5. Alarm logged in air monitoring action spreadsheet?

M1 Thermo Unit alarm was caused by spiders inside of the nephelometer and paper filter. The spiders were vacuumed out of the inlet tube and nephelometer. Unit was recalibrated at 8:30 AM 4/30/13 and inspected at 9:00 AM 4/30/13 to confirm proper function.

