IHC CDF Dredge Project : Air Monitoring Alarm Response Log						
Air Monitoring Station:	X M1	X M2	X M3	□ M4	□ Dock	
Air Monitoring Instrument:						
Cerex Unit (Naphthalene)			articles)	□ PID Monitor		
Date & Time of alarm: <u>7/25/2013 6:00 AM to 8</u> :00PM Email se			Email sent	to site Technician?	(Yes) or No)	
Technician responded to the alarm; Scott Peterson						
1. Was dredging occurring at the time of the alarm?					(Yes or No)	
2. Alarm caused by:						
Loss of Power						
Loss of Radio Communication						
Out of Calibration						
UV Alignment						
Blockage in Air Tube						
X Air Quality						
X Other: Weat	her					
3. Corrective Actions taken?					(Yes or No)	
4. Dredging suspended?				(Yes or No))		
5. Alarm logged in air monitoring action spreadsheet?					(Yes or No	

Description of Action Taken:

A) No problems were found. Dry site condictions and start-up construction traffic for the south ramp entrance project is believe to have caused the alarms.