

IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Station: M1 M2 M3 M4 Dock

Air Monitoring Instrument:

Cerex Unit (Naphthalene) Thermo Unit (Particles) PID Monitor

Date & Time of alarm: 1/1/2013 to 1/3/2014 Email sent to site Technician? ((Yes) or No)

Technician responded to the alarm; Scott Peterson

1. Was dredging occurring at the time of the alarm? (Yes or (No))

2. Alarm caused by:

- Loss of Power
- Loss of Radio Communication
- Out of Calibration
- UV Alignment
- Blockage in Air Tube
- Air Quality
- Other: weather, cold and wind, snow

3. Corrective Actions taken? (Yes or (No))

4. Dredging suspended? (Yes or (No))

5. Alarm logged in air monitoring action spreadsheet? ((Yes) or No)

Description of Action Taken:

A) No problems were found, white-out condition from the snow blowing on top of the dike