IHC CDF Dredge Project: Air Monitoring Alarm Response Log \square M1 \square M2 \mathbf{X} M3 \square M4 □ Dock **Air Monitoring Station: Air Monitoring Instrument:** ▼ Thermo Unit (Particles) ☐ Cerex Unit (Naphthalene) ☐ PID Monitor Date & Time of alarm: <u>02/27/2014 3:45 PM</u> Email sent to site Technician? (Yes)or No) Technician responded to the alarm; Scott Peterson (Yes or No 1. Was dredging occurring at the time of the alarm? 2. Alarm caused by: Loss of Power Loss of Radio Communication Out of Calibration **UV** Alignment Blockage in Air Tube Air Quality Other: weather

(Yes or (No

(Yes or No

Description of Action Taken:

Corrective Actions taken?

5. Alarm logged in air monitoring action spreadsheet?

Dredging suspended?

A) Cold weather and 40 mpg high winds blowing snow caused the Cerex unit to alarm.