IHC CDF Dredge Project : Air Monitoring Alarm Response Log					
Air Monitoring Station:	□ M1	X M2	X M3	□ M4	Dock
Air Monitoring Instrument:□ Cerex Unit (Naphthalene)Image: Structure Stru			articles)	□ PID Monitor	
Date & Time of alarm: <u>6/10/2015 8:00 PM</u> Email sent to site Technic				to site Technician?	(Yes or No)
Technician responded to the alarm; Scott Peterson 1. Was dredging occurring at the time of the alarm? (Yes) or No) 2. Alarm caused by: Loss of Power Loss of Radio Communication Out of Calibration UV Alignment Blockage in Air Tube					
Air QualityXOther: weath	her				
 Corrective Actions taken? Dredging suspended? Alarm logged in air monitoring action spreadsheet? 					(Yes or No) (Yes or No) (Yes or No)

Description of Action Taken:

A) No problems were found wrong with the air unit. High winds and rain storms are believed to caused the alarms.