IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring	Station:	□ M1	□ M2	X M3	□ M4	□ Dock
Air Monitoring Instrument:						
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (Partic			articles)	☐ PID Monito	or	
Date & Time of alarm: <u>7/18/2015 10:00AM</u>				Email sent	to site Technician?	(Yes or No)
Technician responded to the alarm; Scott Peterson						
1. Was dredging occurring at the time of the alarm?						(Yes) or No)
2. Alarm caused by:						
	Loss of Powe	er				
X	Loss of Radio	o Communic	ation			
	Out of Calibr	ration				
	UV Alignme	nt				
Blockage in Air Tube						
	Air Quality					
X	Other: Weath	ner				
3. Corrective Actions taken?					(Yes) or No)	
4. Dredging suspended?						(Yes or (No))
						(Yes) or No)
5. Alarm logged in air monitoring action spreadsheet?						((1es)or No)

Description of Action Taken:

A) Lightning storms stopped communication from the air monitors radio to the administration building radio on 7/17/2015. Air monitor server was re-started on 7/19/2015 and web site started updating correctly.