IHC CDF Dredge Project : Air Monitoring Alarm Response Log \Box M1 \Box M2 X M3 \Box M4 Dock **Air Monitoring Station:** Air Monitoring Instrument: □ Cerex Unit (Naphthalene) X Thermo Unit (Particles) □ PID Monitor Date & Time of alarm: <u>8/18/2015 1:15AM</u> Email sent to site Technician? (Yes)or No) Technician responded to the alarm; Scott Peterson (Yes or No) 1. Was dredging occurring at the time of the alarm? 2. Alarm caused by: Loss of Power Loss of Radio Communication Out of Calibration UV Alignment Blockage in Air Tube Х Air Quality Х Other: Thunder Storms 3. Corrective Actions taken? (Yes or (No) (Yes or No)) 4. Dredging suspended? (Yes) or No) 5. Alarm logged in air monitoring action spreadsheet?

Description of Action Taken:

M3 air alarm during the start of the thunderstorms. Calibration was checked and is when tolerances. Video cameras did not show anything usually.