IHC CDF Dredge Project : Air Monitoring Alarm Response Log **X** M1 X M2 \Box M3 \Box M4 Dock **Air Monitoring Station:** Air Monitoring Instrument: □ Cerex Unit (Naphthalene) X Thermo Unit (Particles) □ PID Monitor Date & Time of alarm: <u>10/12/2015 6:15-8:30</u> Email sent to site Technician? (Yes)or No) Technician responded to the alarm; Scott Peterson (Yes or No) 1. Was dredging occurring at the time of the alarm? 2. Alarm caused by: Loss of Power Loss of Radio Communication Out of Calibration UV Alignment Blockage in Air Tube Х Air Quality Х Other: Windy, dry conditions 3. Corrective Actions taken? (Yes or (No) (Yes or No)) 4. Dredging suspended? (Yes) or No) 5. Alarm logged in air monitoring action spreadsheet?

Description of Action Taken:

The reason for the air alarm is unknown. Air unit calibration was checked and is with-in tolerance.