	IHC CDI	Dredge Pr	oject : Air	Monitoring A	larm Response Log
Air Monitoring Station:	x M1	🖾 M2	🖾 M3	🖾 M4	Dock
Air Monitoring Instrument:□ Cerex Unit (Naphthalene)Image: Thermo Unit (Particular)				\Box PID Monitor	
Date & Time of alarm: 04/15/2016 10:45amEnTechnician responded to the alarm; Scott Peterson				to site Technician?	(Yes)or No)
 Was dredging occurring at the time of the alarm? (Yes or No) Alarm caused by: Loss of Power Loss of Radio Communication Out of Calibration UV Alignment Blockage in Air Tube Air Quality X Other: weather 					
 Corrective Actions tak Dredging suspended? Alarm logged in air m 		on spreadsheet?			(Yes or No) (Yes or No) (Yes or No)

Description of Action Taken:

High winds caused the air unit to alarm. Unit calibration was checked the next day.