	IHC CDI	Dredge Pi	roject : Air I	Monitoring A	larm Response Log	
Air Monitoring Station: Air Monitoring Instrument:	□ M1	🖾 M2	□ M3	□ M4	□ Dock	
□ Cerex Unit (Naphthalene) □ Thermo Unit (Part			articles)	□ PID Monitor		
Date & Time of alarm: <u>05/14/2016</u> 7:00 pm			Email sent	Email sent to site Technician? (Yes)or No)		
Technician responded to the alarm; Scott Peterson						
1. Was dredging occurring at the time of the alarm?					(Yes or No)	
2. Alarm caused by:						
Loss of Power						
Loss of Radio Communication						
Out of Calibration						
UV Alignment						
Blockage in Air Tube						
Air Quality						
X Other: weat	her					
3. Corrective Actions taken?					(Yes or No)	
4. Dredging suspended?					(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)	

Description of Action Taken:

Unknown reason caused the air unit to alarm. Unit calibration was check the next day.