IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Station:	X M1	□ M2	□ M3	X M4	□ Dock
Air Monitoring Instrument:	:				
☐ Cerex Unit (Naphthalene)			Particles)	☐ PID Monitor	
Date & Time of alarm: <u>08/18/2016 All day</u>			Email sent	to site Technician?	Yes or No
Technician responded to the alarm; Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of Power					
Loss of Radio Communication					
Out of Calibration					
UV Alignment					
Blockage in Air Tube					
Air Quality					
X Other: weat	her				
3. Corrective Actions ta	ken?				(Yes or No)
4. Dredging suspended?					(Yes or (No))
5. Alarm logged in air monitoring action spreadsheet? (Ye					(Yes) or No)

Description of Action Taken:

Rain and thunderstorms caused the air units to alarms. Air unit calibrations were checked after the storms passed.