## IHC CDF Dredge Project : Air Monitoring Alarm Response Log

<b>Air Monitoring Station:</b>	□ M1	□ M2	☑ M3	□ M4	□ Dock
<b>Air Monitoring Instrum</b>	ent:				
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (Pa			Particles)	☐ PID Monitor	
Date & Time of alarm: <u>8/8/19 1:45 pm</u>			Email sent	to site Technician?	(Yes)or No)
Technician responded to	the alarm? Scott P	eterson			
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of	Power				
Loss of	Loss of Radio Communication				
Out of O	Out of Calibration				
UV Ali	UV Alignment				
Blockage in Air Tube					
Air Quality					
X Other: u	X Other: unknown, possibility of site maintenance				
3. Corrective Actions taken?					(Yes or No)
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes)or No)

## Description of Action Taken:

Air units was recalibrated. No problems were found during the inspections of the air units.