IH	C CDF Dre	dge Proje	ct : Air Mor	itoring Alar	m Response Log
Air Monitoring Station: Air Monitoring Instrument:	□ M1	□ м2	□ M3	区 M4	□ Dock
Cerex Unit (Naphthalene)	articles)	D PID Monitor			
Date & Time of alarm: 8/20 3:15pmEmail sent to site Technician?Technician responded to the alarm? Scott Peterson					
 Was dredging occurring at the time of the alarm? (Yes or N Alarm caused by: 					(Yes or No)
Loss of Powe Loss of Radio Out of Calibr UV Alignmen Blockage in A Air Quality	o Communicat ation nt	ion			
X Other: unkno 3. Corrective Actions take					(Yes)or No)
4. Dredging suspended?5. Alarm logged in air monitoring action spreadsheet?					(Yes or No) (Yes or No)

Description of Action Taken:

Air units was recalibrated. No problems were found during the inspections of the air units.