

# IHC CDF Dredge Project : Air Monitoring Alarm Response Log

**Air Monitoring Station:**     M1             M2             M3             M4             Dock

**Air Monitoring Instrument:**

Cerex Unit (Naphthalene)             Thermo Unit (Particles)             PID Monitor

Date & Time of alarm: 9/15 11:00 pm

Email sent to site Technician?     Yes or  No

Technician responded to the alarm? Scott Peterson

1. Was dredging occurring at the time of the alarm?            (  Yes or  No )

2. Alarm caused by:

- Loss of Power
- Loss of Radio Communication
- Out of Calibration
- UV Alignment
- Blockage in Air Tube
- Air Quality
- Other: water leaked on to air

monitor

3. Corrective Actions taken?            (  Yes or  No )

4. Dredging suspended?            (  Yes or  No )

5. Alarm logged in air monitoring action spreadsheet?            (  Yes or  No )

***Description of Action Taken:***

Rain water dripped on air unit causing the unit to go out of calibration. Air units was recalibrated.