IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Mo	nitoring	Station:	X M1	□ м2	□ M3	□ M4	Dock
Air Monitoring Instrument:							
Cerex Unit (Naphthalene)				X Thermo Unit (Particles)		□ PID Monitor	
Date & Time of alarm: 01/11/22 3:45 PM to 5:00 PM							
Email sent to site Technician?					(Yes on No)		
Technician responded to the alarm? Scott Peterson							
1.	. Was dredging occurring at the time of the alarm?						(Yes or No)
2. Alarm caused by:							
		Loss of Powe	er				
	Loss of Radio Communication						
		Out of Calibr	ration				
		UV Alignme	nt				
	Blockage in Air Tube						
		Air Quality					
	X	Other: Weath	ner				
3. Corrective Actions taken?						(Yes or No)	
4. Dredging suspended?						(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet? (Yes) or							(Yes) or No)

Description of Action Taken:

A) Cold weather may have caused the air units to alarm. Air units were checked and recalibrated on January 14th.