Inc CDF Dredge Project : Air Monitoring Alarm Response Log					
Air Monitoring Station:	□ M1	X M2	□ M3	\Box M4	Dock
Air Monitoring Instrument:					
□ Cerex Unit (Naphthalene)			D PID Mo	□ PID Monitor	
Date & Time of alarm:07/09/2	2023 16:30				
Email sent to site Technician? (Yes or No))	
Technician responded to the a	larm? Scott Pe	eterson			
1. Was dredging or dike construction occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of Pow	er				
Loss of Radio Communication					
Out of Calibration					
UV Alignment					
Blockage in Air Tube					
? Air Quality					
X Other: Unkn	own Weekend	1/Holiday			
3. Corrective Actions taken?					(Vesor No)
4. Dredging suspended? No dredging operation currently on site.					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)

CDED

Description of Action Taken:

A) It is unknown what caused the high particle reads. The air units were checked and calibrated. No deficiencies were found during inspection. Alarms occurred on the weekend or holiday while no activates or construction was occurring.