IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Instrument: Thermo Scientific Model 5030 Sharp Monitor							
Air Monitor	ring St	ation:□ M1	□ M2	□ M 3	□ M 4	X AM1	□ AM2
Date & Time of alarm: 10/05/2023 4:15-13:00							
	W	Veekend					
	N	Non-Working Hours					
	X A	ctive Contractin	ng On-Site				
Technician responded to the alarm:							
1. Alarm caused by:							
	L	oss of Power					
	L	oss of Radio Co	mmunication				
	L	oss of Cellular	connection				
	О	out of Calibration	n				
	A	ir Quality, Traf	fic, Site Maintenan	nce, Insects			
	X R	ain					
	A	ir Unit Malfunc	tion				
	О	ther					
2. Corrective Actions taken?							
	F	ault Corrected					
	X C	alibration comp	leted				
	S	ite activities sto	pped				
	О	ther					

Description of Action Taken: