
IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Instrument:	Thermo Scientific Model 5030 Sharp Monitor				
Air Monitoring Station: M1	□ м2	□ M3	\Box M4	\Box AM1	X AM2

Date & Time of alarm: <u>10/10/2023 12:45</u>




Technician responded to the alarm:

1. Alarm caused by:

Loss of Power
Loss of Radio Communication
Loss of Cellular connection
Out of Calibration
Air Quality, Traffic, Site Maintenance, Insects
Rain
Air Unit Malfunction
Other

2. Corrective Actions taken?



Description of Action Taken:

High reading is unknown.