## IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitorin	Ionitoring Instrument: Thermo Scientific Model 5030 Sharp Monitor				
Air Monitorin	g Station:□ M1	□ M2	□ M3	□ M4	X AM1 X AM2
Date & Time o	f alarm: <u>11/19/202</u>	3 02:00-4:00			
X	Weekend				
	Non-Working Hours				
	Active Contracting On-Site				
	oonded to the alarr	n:			
1. Alarm caused by:					
	Loss of Power				
X	Loss of Radio Communication				
	Loss of Cellula				
	Out of Calibration				
	Air Quality, Traffic, Site Maintenance, Insects				
	Rain				
	Air Unit Malfu	nction			
X	Other				
2. Corrective Actions taken?					
	Fault Corrected				
X	Calibration con	pleted			
	Site activities s	copped			
	Other				

## Description of Action Taken:

A) It is unknown what is causing the communication failure maybe cellular or web site.