IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Instrument: Thermo Scientific Model 5030 Sharp Monitor						
Air Monitori	ng Station:□ M1	□ M2	□ M 3	□ M 4	X AM1	X AM2
Date & Time of alarm: 12/2/23 10:00-12:30						
	X Weekend					
	Non-Working I	Hours				
	Active Contracting On-Site					
	sponded to the alarr	n:				
1. Alarm caused by:						
	Loss of Power					
	X Loss of Radio C					
	X Loss of Cellula					
	Out of Calibrat	on				
	Air Quality, Tra	affic, Site Maintenand	ce, Insects			
	Rain					
	Air Unit Malfu	nction				
	Other					
2. Corrective Actions taken?						
	Fault Corrected					
	X Calibration con	pleted				
	Site activities s	copped				
	Other					

Description of Action Taken:

A) It is unknown what is causing the communication failure maybe cellular or web site.