## IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitorii	Air Monitoring Instrument: Thermo Scientific Model 5030 Sharp Monitor					
Air Monitorii	ng Station:□ M1	□ M2	□ M3	□ <b>M</b> 4	X AM1	X AM2
Date & Time of alarm: 12/23-12/24 16:45-11:00						
Σ	X Weekend					
	Non-Working I	Hours				
	Active Contract	ing On-Site				
	sponded to the alarr	n:				
1. Alarm	caused by:					
	Loss of Power					
Σ	Loss of Radio C	Communication				
Σ	X Loss of Cellular	connection				
	Out of Calibrati	on				
	Air Quality, Tra	affic, Site Maintenan	ce, Insects			
	Rain					
	Air Unit Malfu	nction				
	Other					
2. Corrective Actions taken?						
	Fault Corrected					
Σ	Calibration con	pleted				
	Site activities st	opped				
	Other					

## Description of Action Taken:

A) It is unknown what is causing the communication failure maybe cellular or web site.