
IHC CDF Dredge Project : Air Monitoring Alarm Response Log


Air Monitoring Instrument:		Thermo Scientific Model 5030 Sharp Monitor					
Air Monitor	ring	Station: M1	□ м2	□ M3	□ M4	□ AM1	X AM2
Date & Time of alarm: <u>03/20/2024 14:30</u>							
		Weekend					
		Non-Working I	Hours				
	X	Active Contrac	ting On-Site				

Technician responded to the alarm:

1. Alarm caused by:



2. Corrective Actions taken?



Description of Action Taken:

- A) It is unknown what is causing the high particle reads. The air units were checked and calibrated. No deficiencies were found during inspection.
- B) Air units are checked and calibrated once a week.