

# IHC CDF Dredge Project : Air Monitoring Alarm Response Log

**Air Monitoring Station:**      M1                     M2                     M3                     M4                     Dock

**Air Monitoring Instrument:**

Cerex Unit (Naphthalene)                     Thermo Unit (Particles)                     PID Monitor

Date & Time of alarm: 9/11/2013 9:15AM                    Email sent to site Technician?      Yes or  No

Technician responded to the alarm; Scott Peterson

1. Was dredging occurring at the time of the alarm?                    ( Yes or  No)

2. Alarm caused by:

- Loss of Power
- Loss of Radio Communication
- Out of Calibration
- UV Alignment
- Blockage in Air Tube
- Air Quality
- Other:

3. Corrective Actions taken?                    ( Yes or  No)

4. Dredging suspended?                    ( Yes or  No)

5. Alarm logged in air monitoring action spreadsheet?                    ( Yes or  No)

**Description of Action Taken:**

A) Radio communications stopped updating because the server started windows updates. Server was restarted and everything is operating normally.