IHC CDF Dredge Project : Air Monitoring Alarm Response Log						
Air Monitoring Station:	□ M1	□ M2	X M3	□ M4	Dock	
Air Monitoring Instrument:						
Cerex Unit (Naphthalene)			articles)	□ PID Monitor		
Date & Time of alarm: <u>9/28/2014 3:00AM</u>			Email sent	to site Technician?	(Yes) or No)	
Technician responded to the alarm; Scott Peterson						
1. Was dredging occurring at the time of the alarm?					(Yes or No	
2. Alarm caused by:						
Loss of Power						
Loss of Radio Communication						
Out of Calibration						
UV Alignment						
Blockage in Air Tube						
Air Quality						
X Other: Wind	server down					
					_	
3. Corrective Actions taken?				(Yes or No)		
4. Dredging suspended?					(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?					(Yes or No)	

Description of Action Taken:

A. USGS weather station lost communication with the web server. Communication was restored within an hour. All units were checked the next day. No problems were found.