## IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Statio	on:	□ M2	X M3	□ M4	□ Dock
Air Monitoring Instru	ıment:				
☐ Cerex Unit (Naphthalene)			Particles)	☐ PID Monito	or
Date & Time of alarm: <u>6/2/2015 8:45</u>			Email sent	to site Technician?	(Yes or No)
Technician responded to the alarm; Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes) or No)
2. Alarm caused by:					
Loss	of Power				
Loss of Radio Communication					
Out of Calibration					
UV Alignment					
Blockage in Air Tube					
Air Quality					
X Other	r:				
2 Compative Act	iona talzan?				(Vac or No
3. Corrective Actions taken?				(Yes or No)	
4. Dredging suspended?				(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)

## Description of Action Taken:

A) No problems were found wrong with the air unit.