U	HC CDF Dr	edge Projec	t : Air Mon	itoring Alarn	n Response Log
Air Monitoring Station: Air Monitoring Instrument	□ M1	🖾 M2	□ M3	□ M4	Dock
Cerex Unit (Naphthalene)			rticles)	□ PID Monit	or
Date & Time of alarm: <u>6/08/19 04:00 pm</u>			Email sent t	Email sent to site Technician? (Yes or No)	
Technician responded to the alarm? Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of Power					
Loss of Radio Communication					
Out of Calibration					
UV Alignment					
Blockage in Air Tube					
Air Quality					
X Other: inse	cts				
3. Corrective Actions taken?					(Yes or No)
4. Dredging suspended?				(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?					(Ves) or No)

Description of Action Taken:

A) A small spider was found in the inlet tube. Air unit was cleaned and recalibrated.