## IHC CDF Dredge Project : Air Monitoring Alarm Response Log $\square$ M1 $\square$ M2 X M3 $\Box$ M4 Dock **Air Monitoring Station: Air Monitoring Instrument:** Cerex Unit (Naphthalene) I Thermo Unit (Particles) □ PID Monitor Date & Time of alarm: <u>1/10/20 8:00 PM</u> (Yes)or No) Email sent to site Technician? Technician responded to the alarm? Scott Peterson (Yes or No) 1. Was dredging occurring at the time of the alarm? 2. Alarm caused by: Loss of Power Loss of Radio Communication Out of Calibration UV Alignment Blockage in Air Tube Air Quality Х Other: unknown 3. Corrective Actions taken? (Yes or(No)) 4. Dredging suspended? (Yes or (No)) (Yes) or No) 5. Alarm logged in air monitoring action spreadsheet?

## Description of Action Taken:

No problems found during air monitor inspection. Weather may have contribute to the high particles readings. Air unit was recalibrated on 1/13/2019.