		IC CDF Dr	edge Projec	t : Air Mon	itoring Alarr	n Response Log
Air Monitoring		□ м1	X M2	X M3	□ M4	□ Dock
Air Monitoring			Thermo Unit (Pa	articles)	□ PID Monit	or
Date & Time of alarm: 7/03/2020 7/04/2020 10:45-3:15 Email sent to site Technician?						(Yes of No)
	dging occurri aused by: Loss of Pow	ng at the time ver io Communica	of the alarm?			(Yes or No))
X	UV Alignm Blockage in Air Quality Other: weath	Air Tube				
3. Correcti	3. Corrective Actions taken?					
4. Dredging suspended?						(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?						(Yes) or No)

Description of Action Taken:

High winds during the night caused high readings. Unit was check the next morning no faults found.