IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Instrument:	
☐ Cerex Unit (Naphthalene)	
Date & Time of alarm: 10/16/20 10:45pm Email sent to site Technician? (Ye	s or No
Technician responded to the alarm? Scott Peterson	
1. Was dredging occurring at the time of the alarm? (Yes	or(No)
2. Alarm caused by:	
Loss of Power	
Loss of Radio Communication	
Out of Calibration	
UV Alignment	
Blockage in Air Tube	
Air Quality	
X Other: Unknown	
3. Corrective Actions taken? (Yes)	or No)
4. Dredging suspended? (Yes	or No)
5. Alarm logged in air monitoring action spreadsheet? (Yes)	or No)

Description of Action Taken:

A) Unknown what caused the alarms. No activities were happening on site during the alarms. M1 air unit was checked and recalibrated.