IHC CDF Dredge Project : Air Monitoring Alarm Response Log X M1 \square M2 \Box M3 \Box M4 Dock **Air Monitoring Station:** Air Monitoring Instrument: Cerex Unit (Naphthalene) I Thermo Unit (Particles) □ PID Monitor Date & Time of alarm: <u>10/22/20 2:45pm</u> Email sent to site Technician? (Yes on No) Technician responded to the alarm? Scott Peterson (Yes or No) 1. Was dredging occurring at the time of the alarm? 2. Alarm caused by: Loss of Power Loss of Radio Communication Out of Calibration **UV** Alignment Blockage in Air Tube Air Quality Other: Unknown Х ((Yes) or No) 3. Corrective Actions taken? (Yes or No)) 4. Dredging suspended? (Yes) or No) 5. Alarm logged in air monitoring action spreadsheet?

Description of Action Taken:

A) Unknown what caused the alarms crew were working on top of the dike moving pipes in the cells. M1 air unit was checked and recalibrated.