## IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Statio	on:	<b>⊠</b> M2	□ M3	□ M4	□ Dock
Air Monitoring Instrument:					
☐ Cerex Unit (Naphthalene)		articles)	☐ PID Monite	or	
Date & Time of alarm: <u>2/10/21</u>			Email sent	to site Technician?	(Yes on No)
Technician responded to the alarm? Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss	of Power				
Loss	Loss of Radio Communication				
Out of	Out of Calibration				
UV Alignment					
Blockage in Air Tube					
Air Quality					
Other:	Other: Unknown				
3. Corrective Actions taken?					(Yes or No)
4. Dredging suspended?				(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?				(Yes)or No)	

## Description of Action Taken:

A) Unsure of what caused the high particle readings. Air unit was checked and calibration completed on 2/11/2021.