IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Instrument: Thermo Scientific Model 5030 Sharp Monitor							
Air Monitor	ing Station:□	M1	□ M2	□ M3	□ M4	X AM1	□ AM2
Date & Time of alarm: <u>10/11/2023 10:15-11:15</u>							
	Weekend	I					
-	Non-Wor	king Hours					
	X Active C	ontracting On	n-Site				
Technician responded to the alarm:							
1. Alarm caused by:							
	Loss of P	ower					
-	Loss of R	Radio Comm	unication				
-	Loss of C	Cellular conn	ection				
-	Out of Ca	alibration					
-	Air Qual	ity, Traffic, S	Site Maintenan	ce, Insects			
-	X Rain						
-	Air Unit	Malfunction					
-	Other						
2. Corrective Actions taken?							
	Fault Con	rected					
-	X Calibration	on completed	l				
-	Site activ	rities stopped					
	Other						

Description of Action Taken: