

# IHC CDF Dredge Project : Air Monitoring Alarm Response Log

**Air Monitoring Station:**     M1             M2             M3             M4             Dock

**Air Monitoring Instrument:**

Cerex Unit (Naphthalene)             Thermo Unit (Particles)             PID Monitor

Date & Time of alarm: 8/14 thru 8/17

Email sent to site Technician?    (Yes or No)

Technician responded to the alarm? Scott Peterson

1. Was dredging occurring at the time of the alarm?            ( Yes or No)

2. Alarm caused by:

- |                                     |                                 |
|-------------------------------------|---------------------------------|
| <input type="checkbox"/>            | Loss of Power                   |
| <input checked="" type="checkbox"/> | Loss of Radio Communication     |
| <input type="checkbox"/>            | Out of Calibration              |
| <input type="checkbox"/>            | UV Alignment                    |
| <input type="checkbox"/>            | Blockage in Air Tube            |
| <input type="checkbox"/>            | Air Quality                     |
| <input checked="" type="checkbox"/> | Other: unknown, windows update. |

3. Corrective Actions taken?            ( Yes or No)

4. Dredging suspended?            ( Yes or No)

5. Alarm logged in air monitoring action spreadsheet?            (Yes or No )

***Description of Action Taken:***

Admin server computer updated Windows 10 but did not restart correctly. Re-stated the computer with no faults.