

IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Station: M1 M2 M3 M4 Dock

Air Monitoring Instrument:

Cerex Unit (Naphthalene) Thermo Unit (Particles) PID Monitor

Date & Time of alarm: 8/19 10:15 PM

Email sent to site Technician? Yes or No

Technician responded to the alarm? Scott Peterson

1. Was dredging occurring at the time of the alarm? Yes or No

2. Alarm caused by:

- | | |
|-------------------------------------|---|
| <input type="checkbox"/> | Loss of Power |
| <input type="checkbox"/> | Loss of Radio Communication |
| <input type="checkbox"/> | Out of Calibration |
| <input type="checkbox"/> | UV Alignment |
| <input type="checkbox"/> | Blockage in Air Tube |
| <input type="checkbox"/> | Air Quality |
| <input checked="" type="checkbox"/> | Other: unknown, maybe caused by small insects |

3. Corrective Actions taken? Yes or No

4. Dredging suspended? Yes or No

5. Alarm logged in air monitoring action spreadsheet? Yes or No

Description of Action Taken:

Air units was recalibrated. No problems were found during the inspections of the air units.