IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitoring Station:	⊠ M1 □	M2 ====================================	□ M3	□ M4	
☐ Cerex Unit (Naphtha	llene) 🛭 Thermo	Unit (Particles)		Monitor	
Date & Time of alarm: 11/18/2012 3:00 AM Email sent to site Technician (Yes) or No).					
Technician responded to the alarm: Scott Peterson					
Out of 0	Power Radio Communica Calibration gnment ge in Air Tube	ation			
2. Corrective Actions taken (Yes) or No).					
3. Dredging suspended (Yes or No).					

Description of Action Taken:

M4 Thermo Unit alarm was caused by spiders inside of the naphelometer and paper filter. The spiders were vacuumed out of the inlet tube and naphelometer. Unit was recalibrated at 7:00 AM 11/18/12 and inspected at 11:00 AM 11/18/12 to confirm proper function.

4. Alarm logged in air monitoring action spreadsheet. (Yes) or No).

