
IHC CDF Dredge Project : Air Monitoring Alarm Reponse Log				
Air Monitoring Station: 🖾 M1	□ M2	□ м3	□ M4	
Cerex Unit (Naphthalene) Thermo Unit (Particles) D PID Monitor				
Date & Time of alarm: <u>11/15/2012_9</u>	9:30 PM	Email sent	to site Technician	(Yes) or No).
1. Alarm cause by:				



- 2. Corrective Actions taken (Yes) or No).
- 3. Dredging suspended (Yes or No)).
- 4. Alarm logged in air monitoring action spreadsheet. (Yes) or No).

Description of Action Taken:

M1 Thermo Unit alarm was caused by spiders inside of the naphelometer and paper filter. The spiders were vacuumed out of the inlet tube and naphelometer. Unit was recalibrated at 7:30 AM 11/16/12 and inspected at 9:00 AM 11/16/12 to confirm proper function.

