IHC CDF Dredge Project : Air Monitoring Alarm Response Log						
Air Monitoring Station:	□ M1	□ M2	□ M3	X M4	□ Dock	
Air Monitoring Instrument:						
Cerex Unit (Naphthalene)			articles)	□ PID Monitor		
Date & Time of alarm: <u>1/11/2013_3:30 PM</u>			Email sent	to site Technician?	(Yes) or No)	
Technician responded to the alarm; Scott Peterson						
1. Was dredging occurring at the time of the alarm?				(Yes or No		
2. Alarm caused by:						
Loss of Power						
Loss of Radio Communication						
Out of Calibration						
UV Alignment						
Blockage in Air Tube						
Air Quality						
X Other: W	eather					
					-	
3. Corrective Actions taken?				(Yes or No)		
4. Dredging suspended?				(Yes or No)		
5. Alarm logged in air monitoring action spreadsheet?					(Yes or No)	

Description of Action Taken:

For unknown reasons the M4 Thermo unit alarm. Unit was inspected at 8:30 AM 1/11/13 to confirm proper functions.