IHC CDF Dredge Project: Air Monitoring Alarm Response Log

(Yes or No)

Air Monitoring Station:	⊠ M1	□ M2	□ M 3	□ M4	□ Dock
Air Monitoring Instrument:					
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (Parti			ticles)	☐ PID Monitor	
Date & Time of alarm: <u>5/08/2013 7:00 AM</u>			Email sent	mail sent to site Technician? (Yes) or No)	
Technician responded to the alarm; Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of Power	•				
Loss of Radio Communication					
Out of Calibration					
UV Alignment					
X Blockage in Air Tube					
Air Quality					
Other: Weath	er				
3. Corrective Actions taken?					(Yes) or No)
4. Dredging suspended?			(Yes or (No))		

Description of Action Taken:

5. Alarm logged in air monitoring action spreadsheet?

M1 Thermo Unit alarm was caused by spiders inside of the nephelometer and paper filter. The spiders were vacuumed out of the inlet tube and nephelometer. Unit was recalibrated at 8:30 AM 5/08/13 and inspected at 15:00 AM 5/08/13 to confirm proper function.

