IHC CDF Dredge Project : Air Monitoring Alarm Response Log						
Air Monitoring Station:		□ M1	X M2	□ м3	□ M4	□ Dock
Air Monitoring Instrument:						
Cerex Unit (Naphthalene)			Thermo Unit (Par	icles)		
Date & Time of alarm: <u>9/11/2013 12:45AM</u>			Email sent	to site Technician?	(Yes or No)	
Technician responded to the alarm; Scott Peterson						
1. Was dredging occurring at the time of the alarm?						(Yes or No)
2. Alarm caused by:						
	Loss of Powe	r				
X	X Loss of Radio Communication					
Out of Calibration						
UV Alignment						
Blockage in Air Tube						
Air Quality						
X	Other: weathe	er				
3. Corrective Actions taken?					(Yes or No)	
4. Dredging suspended?					(Yes or No))	
5. Alarm logged in air monitoring action spreadsheet?					(Yes or No)	

Description of Action Taken:

A) No problems were found.