	IHC CDI	Dredge Pr	oject : Air I	Monitoring Al	arm Response Log
Air Monitoring Station:	\Box M1	X M2	□ м3	□ M4	Dock
Air Monitoring Instrument:					
Cerex Unit (Naphthalene)			articles)	□ PID Monito	DL
Date & Time of alarm: <u>03/1/2014 10:15 PM</u>			Email sent	to site Technician?	(Yesor No)
Technician responded to the alarm; Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of Power					
Loss of Radio Communication					
Out of Calibration					
UV Alignment					
Blockage in Air Tube					
Air Quality					
X Other: weath	ier				
3. Corrective Actions taken?					(Yes or No)
4. Dredging suspended?					(Yes or No)
 Alarm logged in air monitoring action spreadsheet? 					(Yes or No)

Description of Action Taken:

A) Unit was checked and no problems were found.