\square M1 \square M2 \square M3 X M4 □ Dock **Air Monitoring Station: Air Monitoring Instrument:** X Thermo Unit (Particles) ☐ PID Monitor ☐ Cerex Unit (Naphthalene) Date & Time of alarm: <u>5/06/2014 7:00am-10:3</u>0am Email sent to site Technician? (Yes)or No) Technician responded to the alarm; Scott Peterson (Yes or No 1. Was dredging occurring at the time of the alarm? 2. Alarm caused by: Loss of Power Loss of Radio Communication Out of Calibration **UV** Alignment Blockage in Air Tube Air Quality Other: weather, wind Corrective Actions taken? (Yes or No Dredging suspended? (Yes or (No))

IHC CDF Dredge Project: Air Monitoring Alarm Response Log

(Yes) or No)

Description of Action Taken:

A) No problems were found with the air units.

5. Alarm logged in air monitoring action spreadsheet?