## IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Station:	<b>⊠</b> M1	X M2	X M3	X M4	□Dock
Air Monitoring Instrum	ent:				
☐ Cerex Unit (Naphthalene)		Thermo Unit (P	articles)	☐ PID Monito	or
Date & Time of alarm: <u>5/30/2014 9:15</u>			Email sent	to site Technician?	(Yes)or No)
Technician responded to the alarm; Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of P	ower				
Loss of Radio Communication					
Out of Calibration					
UV Alignment					
Blockage in Air Tube					
Air Quality					
X Other: un	known				
3. Corrective Actions taken?					(Yes or No
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)

## Description of Action Taken:

o All units were checked but no problems were found.