	IHC CDI	Dredge Pr	oject : Air I	Monitoring A	larm Response Log	
Air Monitoring Station:	X M1	X M2	X M3	X M4	□ Dock	
Air Monitoring Instrument:						
Cerex Unit (Naphthalene)			Particles)	□ PID Monitor		
Date & Time of alarm: <u>6/1/2014 8:30</u>			Email sent	to site Technician?	(Yesor No)	
Technician responded to the alarm; Scott Peterson						
 Was dredging occurring at the time of the alarm? Alarma areas a here 					(Yes) or No)	
2. Alarm caused by:						
Loss of Power						
Loss of Radio Communication						
Out of Calibration						
UV Alignment						
Blockage in Air Tube						
Air Quality						
X Other: unknow	wn					
3. Corrective Actions taken?				(Yes or No)		
4. Dredging suspended?					(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)	

Description of Action Taken:

• All units were checked but no problems were found.