	IHC CDF	Dredge Pro	ject : Air I	Monitoring Al	larm Response Log
Air Monitoring Station:	X M1	X M2	X M3	X M4	Dock
Air Monitoring Instrument:					
Cerex Unit (Naphthalene)	x ,	Thermo Unit (Par	ticles)	□ PID Monite	or
Date & Time of alarm: 6/26/2014 11:30- 6/27/2014-8:00AM Email sent to site Technicia				to site Technician?	(Yes)or No)
Technician responded to the alarm; Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Ves or No)
2. Alarm caused by:					
Loss of Power					
Loss of Radio Communication					
Out of Calibration					
UV Alignment					
Blockage in Air Tube					
Air Quality					
X Other: Weath	er Fog				
3. Corrective Actions taken?				(Yes or No	
4. Dredging suspended?				(Yes or No))	
5. Alarm logged in air monitoring action spreadsheet?				(Yes) or No)	

Description of Action Taken:

• Alarms were caused from heavy fog.