IHC CDF Dredge Project: Air Monitoring Alarm Response Log

Air Monitoring Station:	X M1	X M2	☑ M3	⊠ M4	□ Dock
Air Monitoring Instrument:					
☐ Cerex Unit (Naphthalene) ☐ Thermo Unit (Pa			articles)	☐ PID Monitor	
Date & Time of alarm: 1/9/20)15		Email sent	to site Technician?	(Yes)or No)
Technician responded to the alarm; Scott Peterson					
1. Was dredging occurring at the time of the alarm?					(Yes or No)
2. Alarm caused by:					
Loss of Power	r				
Loss of Radio Communication					
Out of Calibration					
UV Alignment					
Blockage in Air Tube					
Air Quality					
X Other: weather	r, cold and w	indy, snowing			
3. Corrective Actions taken?				(Yes or No)	
4. Dredging suspended?					(Yes or No)
5. Alarm logged in air monitoring action spreadsheet?					((Yes) or No)

Description of Action Taken:

A) No problems were found, winter storm causing white-out condition from the snow blowing on top of the dike.