\square M1 \mathbf{X} M2 \square M3 \square M4 □ Dock **Air Monitoring Station: Air Monitoring Instrument:** ☐ Cerex Unit (Naphthalene) X Thermo Unit (Particles) ☐ PID Monitor Date & Time of alarm: <u>5/04/2015 5:00 PM</u> Email sent to site Technician? (Yes or(No)) Technician responded to the alarm; Scott Peterson (Yes or No 1. Was dredging occurring at the time of the alarm? 2. Alarm caused by: Loss of Power Loss of Radio Communication Out of Calibration **UV** Alignment Blockage in Air Tube Air Quality Other: weather, windy 3. Corrective Actions taken? (Yes or No

IHC CDF Dredge Project: Air Monitoring Alarm Response Log

(Yes or No)
(Yes) or No)

Description of Action Taken:

A) No problems were found.

Dredging suspended?

5. Alarm logged in air monitoring action spreadsheet?