## IHC CDF Dredge Project : Air Monitoring Alarm Response Log

Air Monitoring Station:	□ M1	☑ M2	☑ M3	□ M4	□ Dock	
Air Monitoring Instrument:						
☐ Cerex Unit (Naphthalene)		articles)	☐ PID Monite	or		
Date & Time of alarm: <u>5/09/2015 10:00 PM</u>			Email sent	nail sent to site Technician? (Yes or No)		
Technician responded to the alarm; Scott Peterson						
1. Was dredging occurring at the time of the alarm?					(Yes or No)	
2. Alarm caused by:						
Loss of Powe	r					
Loss of Radio	Loss of Radio Communication					
Out of Calibration						
UV Alignmer	UV Alignment					
Blockage in Air Tube						
Air Quality						
X Other: weather	er, Fog					
3. Corrective Actions taken?				(Yes or No)		
4. Dredging suspended?					(Yes or No)	
5. Alarm logged in air monitoring action spreadsheet?					(Yes) or No)	

## Description of Action Taken:

A) No problems were found. Fog caused the alarm.

Air Unit